

E26 92R-011107



**ECE Type-Approval Certificate**  
for non-original motorcycle exhaust



<b>Approval No.:</b>	E26 92R-011107
<b>Issued by:</b>	SLOVENIAN TRAFIC SAFETY AGENCY Vehicle department Kotnikova ulica 19a, SI-1000 LJUBLJANA, SLOVENIA
<b>Place &amp; date of type-approval:</b>	LJUBLJANA, 17.2.2015
<b>Report No.:</b>	15-00023-CM-GBM-00
<b>Issued by:</b>	TÜV SÜD Auto Service GmbH Westendstrasse 199 DE-80686 MÜNCHEN
<b>Date of issue:</b>	12.2.2015
<b>Approval identification:</b>	E26 92R-011107

Technical data of exhaust system

**Type and version of exhaust:** M-HRD41 / M-HRD410IT, M-HRD410ISS, M-HRD4102T, M-HRD4102SS, M-HRD4103T, M-HRD4103SS, M-HRD4104T, M-HRD4104SS, M-HRD4105T, M-HRD4105SS.

**Marking:** Engraved by laser / plate fixed with rivets.

**Field of application:**

Manufacturer / Trade mark	Commercial description	Vehicle type (and no. of homologation)	Engine type	Component parts, dimensions in mm	Dimensions of the part in mm or original part / replacement part	Akrapovic part no. Or homologation no.
YAMAHA Motor Espana S.A. / YAMAHA	X-MAX 250 / YP 250 R X-MAX 250 / YP 250 R	SG16 (e9*0039*) SG22 (e9*0362*)	G344E / G362E G389E / G3A7E	Header pipes Header pipes	Original parts -	- H-xxx
M.B.K. Industrie (F) / YAMAHA	X-MAX 250 / YP 250 R X-MAX 250 / YP 250 R X-MAX 125 / YP 125 R X-MAX 125 / YP 125 R	SG25 (e13*0494*) SG26 (e13*0680*) SE64 (e13*0501*) SE68 (e13*0654*)	G389E / G3A7E G3B3E E362E E3M1E	Link pipe Catalytic converter Catalytic converter Catalytic converter	- ø 62 x 65 ø 62 x 65 ø 62 x 65	L-xxx P-KAT-028, ø24*0150*(5) P-KAT-039, ø26*1063*(5) P-KAT-040, ø26*1063*(5)
YAMAHA Motor Espana S.A. / YAMAHA	X-MAX 125 / YP 125 R X-MAX 125 / YP 125 R	SE32 (e9*0052*) SE54 (e9*0395*)	E384E E362E	Silencer (Outlet pipe ø 22)	Hexagonal 113 x 143 Length without end caps 350	M-HRD41, ø24*0242*(9) E26 92R 011107
M.B.K. Industrie (F) / YAMAHA	X-City 250 / YP 250 X-City 125	SG19 (e13*0190*) SE43 (e13*0203*)	G358E E3A5E			
YAMAHA Motor Espana S.A. / MBK	Scycruiser 125 Scycruiser 125 Scycruiser 250	SE32 (e9*0052*) SE54 (e9*0395*) SG22 (e9*0362*)	E384E E362E G389E / G3A7E			
M.B.K. Industrie (F) / MBK	Scycruiser 125 Scycruiser 125 Scycruiser 250 Scycruiser 250 Cityliner 125	SE64 (e13*0501*) SE68 (e13*0654*) SG25 (e13*0494*) SG26 (e13*0680*) SE43 (e13*0203*)	E362E E3M1E G389E / G3A7E G3B3E E3A5E			
HONDA (I)	SH 125 SH 150 PCX 125 PCX 125 PCX 150 PCX 150	JF41 (e4*2896*) KF13 (e4*2897*) JF47 (e13*0585*) JF57 (e4*3061*) KF15 (e13*0586*) KF19 (e4*3063*)	JF41E KF13E JF47E JF57E KF15E KF19E			
HONDA (V)	PCX 125 PCX 150	JF56 (e4*3060*) KF18 (e4*3062*)	JF56E KF18E			
Thai Honda Co.Ltd. / Honda	PCX 125 PCX 150	JF28 (e13*0373*) KF12 (e13*0548*)	JF28E KF12E			

## To be filled out by Akrapovič representative:

Date of purchase:

Issued by:

Stamp & signature:

## Muffler repack kit service intervals

The durability of the damping material depends on the type of motorcycle, riding style, mileage etc. Normally, single and twin cylinder engines produce a stronger exhaust gas wave pulse and a higher temperature. Often, riding on a race track requires noise control. The insulating material should be replaced when you notice any visual changes on the muffler sleeve material or when the muffler exceeds the noise limit. Please check the muffler visually before every season.

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp & signature: \_\_\_\_\_

## Maintenance

1. Clean the titanium muffler outer sleeves with a multi-purpose spray lubricant (WD-40 or equivalent) and carbon-fiber outer sleeves with soft and dry cloth. Do not use aggressive chemical cleaners, because they can damage the sticker. A change in the color of the exhaust system is normal due to the high temperatures.

2. The wearing out of the muffler silencing material depends on the type of the motor and riding style. Contact your dealer/serviceman if visible changes appear on muffler's outer sleeve or the noise level is increased.

3. Periodically make sure all the bolts are sufficiently tight.

## Exclusion of Certain Liability

1. The manufacturer, importer or dealer shall not be liable for any incidental damage including personal injury or any other damages caused by improper installation or operation of the Akrapovič exhaust system. When installing the Akrapovič exhaust system be careful that the exhaust system does not touch other parts sensitive to high temperature.

2. Akrapovič makes no representation or warranties with regard to damage caused by the improper installation, use and maintenance of the Akrapovič exhaust system. The warranty is limited to defects recognized by our technical department and to normal use, and excludes items subject to normal wear (gaskets and damping wool). The guarantee is void in case of accident, modification, improper or competition use.

3. Do not attempt to install the Akrapovič exhaust system on a motorcycle for which it was not made or tested by Akrapovič.

4. When the exhaust system gets very hot during operation, be careful not to burn yourself on the exhaust system or parts which are in direct contact with it, even when the motor is not running. Also protect other people, especially children, from the injuries mentioned above.

5. In some cases Akrapovič exhaust system kits contain chemical products (ceramic anti-seizing grease). Handle with care, do not inhale or swallow. Avoid excessive contact with skin, eyes or mucous membranes. Keep out of the reach of children.

6. Technical specifications of Akrapovič exhaust systems and related products subject to change without notice.

e24 0242 (9)



## EC Type-Approval Certificate

for non-original motorcycle exhaust system



\*503970\*

Approval No.:	e24*97/24*2009/108/9/III*0242*01
Issued by:	NATIONAL STANDARDS AUTHORITY OF IRELAND Certification Services - Operations Manufacturing 1 swift Square, Northwood, Santry, Dublin 9, Ireland
Place & date of type-approval:	Dublin, 03.03.2015
Report No.:	13-00138-CM-GBM-01
Issued by:	TÜV SÜD Auto Service GmbH Westendstrasse 199 DE-80686 MÜNCHEN
Date of issue:	04.02.2015
Approval identification:	e24 0242 (9)

**Type and version of exhaust:** M-HRD41 / M-HRD410IT, M-HRD410ISS, M-HRD4102T, M-HRD4102SS, M-HRD4103T, M-HRD4103SS, M-HRD4104T, M-HRD4104SS, M-HRD4105T, M-HRD4105SS.

**Marking:** Engraved by laser / plate fixed with rivets.

### Field of application:

Manufacturer / Trade mark	Commercial description	Vehicle type (and no. of homologation)	Engine type	Component parts, dimensions in mm	Dimensions of the part in mm or original part / replacement part	Akrapovic part no. Or homologation no.
YAMAHA Motor Espana S.A. / YAMAHA	X-MAX 250 / YP 250 R	SG16 (e9*0039*)	G344E / G362E	Header pipes	Original parts	-
M.B.K. Industrie (F) / YAMAHA	X-MAX 250 / YP 250 R	SG22 (e9*0362*)	G389E / G3A7E	Header pipes	-	H-xxx
	X-MAX 250 / YP 250 R	SG25 (e13*0494*)	G389E / G3A7E	Link pipe	-	L-xxx
	X-MAX 125 / YP 125 R	SE26 (e13*0680*)	G3B3E	Catalytic converter	ø 62 x 65	P-KAT-028, e24*0150*(5)
	X-MAX 125 / YP 125 R	SE64 (e13*0501*)	E3B2E	Catalytic converter	ø 62 x 65	P-KAT-039, e26*1063*(5)
	X-MAX 125 / YP 125 R	SE68 (e13*0654*)	E3M1E	Catalytic converter	ø 62 x 65	P-KAT-040, e26*1069*(5)
YAMAHA Motor Espana S.A. / YAMAHA	X-MAX 125 / YP 125 R	SE32 (e9*0052*)	E3B4E	Silencer	Hexagonal 113 x 143	M-HRD41, e24*0242*(9)
	X-MAX 125 / YP 125 R	SE54 (e9*0395*)	E3B2E	(Outlet pipe ø 22)	Length without end caps 350	E26 92R DI 1107
M.B.K. Industrie (F) / YAMAHA	X-City 250 / VP 250	SE19 (e13*0190*)	G358E			
	X-City 125	SE43 (e13*0203*)	E3A5E			
YAMAHA Motor Espana S.A. / MBK	Scyrcruiser 125	SE32 (e9*0052*)	E3B4E			
	Scyrcruiser 125	SE54 (e9*0395*)	E3B2E			
	Scyrcruiser 250	SG22 (e9*0362*)	G389E / G3A7E			
M.B.K. Industrie (F) / MBK	Scyrcruiser 125	SE64 (e13*0501*)	E3B2E			
	Scyrcruiser 125	SE68 (e13*0654*)	E3M1E			
	Scyrcruiser 250	SG25 (e13*0494*)	G389E / G3A7E			
	Scyrcruiser 250	SG26 (e13*0680*)	G3B3E			
	Cityliner 125	SE43 (e13*0203*)	E3A5E			
HONDA (I)	SH 125	JF41 (e4*2896*)	JF41E			
	SH 150	KF13 (e4*2897*)	KF13E			
	PCX 125	JF47 (e13*0585*)	JF47E			
	PCX 125	JF57 (e4*3061*)	JF57E			
	PCX 150	KF15 (e13*0586*)	KF15E			
	PCX 150	KF19 (e4*3063*)	KF19E			
HONDA (V)	PCX 125	JF56 (e4*3060*)	JF56E			
	PCX 150	KF18 (e4*3062*)	KF18E			
Thai HONDA Co.Ltd / HONDA	PCX 125	JF28 (e13*0373*)	JF28E			
	PCX 150	KF12 (e13*0548*)	KF12E			

## To be filled out by Akrapovič representative:

Date of purchase: Issued by: 

Stamp &amp; signature:

## Muffler repack kit service intervals

The durability of the damping material depends on the type of motorcycle, riding style, mileage etc. Normally, single and twin cylinder engines produce a stronger exhaust gas wave pulse and a higher temperature. Often, riding on a race track requires noise control. The insulating material should be replaced when you notice any visual changes on the muffler sleeve material or when the muffler exceeds the noise limit. Please check the muffler visually before every season.

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

Date: \_\_\_\_\_

Performed by: \_\_\_\_\_

Stamp &amp; signature: \_\_\_\_\_

## Maintenance

1. Clean the titanium muffler outer sleeves with a multi-purpose spray lubricant (WD-40 or equivalent) and carbon-fiber outer sleeves with soft and dry cloth. Do not use aggressive chemical cleaners, because they can damage the sticker. A change in the color of the exhaust system is normal due to the high temperatures.

2. The wearing out of the muffler silencing material depends on the type of the motor and riding style. Contact your dealer/serviceman if visible changes appear on muffler's outer sleeve or the noise level is increased.

3. Periodically make sure all the bolts are sufficiently tight.

## Exclusion of Certain Liability

1. The manufacturer, importer or dealer shall not be liable for any incidental damage including personal injury or any other damages caused by improper installation or operation of the Akrapovič exhaust system. When installing the Akrapovič exhaust system be careful that the exhaust system does not touch other parts sensitive to high temperature.

2. Akrapovič makes no representation or warranties with regard to damage caused by the improper installation, use and maintenance of the Akrapovič exhaust system. The warranty is limited to defects recognized by our technical department and to normal use, and excludes items subject to normal wear (gaskets and damping wool). The guarantee is void in case of accident, modification, improper or competition use.

3. Do not attempt to install the Akrapovič exhaust system on a motorcycle for which it was not made or tested by Akrapovič.

4. When the exhaust system gets very hot during operation, be careful not to burn yourself on the exhaust system or parts which are in direct contact with it, even when the motor is not running. Also protect other people, especially children, from the injuries mentioned above.

5. In some cases Akrapovič exhaust system kits contain chemical products (ceramic anti-seizing grease). Handle with care, do not inhale or swallow. Avoid excessive contact with skin, eyes or mucous membranes. Keep out of the reach of children.

6. Technical specifications of Akrapovič exhaust systems and related products subject to change without notice.